

✓

TOTAL INSPECTIONS
127
TREND ▲ 100%

+




POSITIVE OBSERVATIONS
1,331
TREND ▲ 100%

—

NEGATIVE OBSERVATIONS
397
TREND ▲ 100%

🗑️


TOTAL OBSERVATIONS
1,728
TREND ▲ 100%




Top 10 Negative Observations

Rank	Sub-Category	Count
1	Both feet on floor of basket? 1926.453(b)(2)(iv)	18
2	Top of ladder secured to prevent side shift? 1926.1053(b)(1)	15
3	Workers tied off to approved anchorage point in basket? 1926.453(b)(2)	13
4	Chemicals (in secondary container) properly labeled/legible? 1910.1200	10
5	Operator(s) trained and/or authorized? 1926.453(b)(2)(ii)	6
6	Flexible cords maintained in good condition? 1926.416(e)(1)	5
7	Radius guard installed on crane? 1926.1424(a)	5
8	Aisles/passageways appropriately marked? 1910.22(b)(2) Interp Letter	5
9	Lifting hooks have functional safety latch? 1910.179(j)(2)(iii)	5
10	Rigging equipment properly tagged/labeled? 1926.251(a)(2)(i)(iii)	5


Inspections by Company




Average Score by Company



Inspections by Inspector







Average Score by Inspector




eCAT Dashboard

Use this dashboard To analyze your Corrective Action Tracking.



1/1/2018 - 11/30/2018



Open: 151
Pending: 4
Closed: 122

1/1/2018 - 11/30/2018

	Open	Pending	Closed	% Closed
NOV 2018	8	0	9	53%
OCT 2018	36	0	11	23%
SEP 2018	4	0	4	50%
AUG 2018	0	0	8	100%
JUL 2018	32	1	24	42%
JUN 2018	10	0	9	47%
MAY 2018	25	1	20	43%
APR 2018	5	0	18	78%
MAR 2018	24	2	12	32%
FEB 2018	7	0	4	36%
JAN 2018	0	0	3	100%
DEC 2017	0	0	0	0%
NOV 2017	0	0	0	0%